



MB106A

**1 pole, Curve B, 6/10 kA**

Description	Pack qty.	Art No.
MCB 1P 6kA B-6A 1M	12	<b>MB106A</b>
MCB 1P 6kA B-10A 1M	12	<b>MB110A</b>
MCB 1P 6kA B-16A 1M	12	<b>MB116A</b>
MCB 1P 6kA B-20A 1M	12	<b>MB120A</b>
MCB 1P 6kA B-25A 1M	12	<b>MB125A</b>
MCB 1P 6kA B-32A 1M	12	<b>MB132A</b>
MCB 1P 6kA B-40A 1M	12	<b>MB140A</b>
MCB 1P 6kA B-50A 1M	12	<b>MB150A</b>
MCB 1P 6kA B-63A 1M	12	<b>MB163A</b>



MB210A

**2 pole, Curve B, 6/10 kA**

Description	Pack qty.	Art No.
MCB 2P 6kA B-6A 2M	6	<b>MB206A</b>
MCB 2P 6kA B-10A 2M	6	<b>MB210A</b>
MCB 2P 6kA B-16A 2M	6	<b>MB216A</b>
MCB 2P 6kA B-20A 2M	6	<b>MB220A</b>
MCB 2P 6kA B-25A 2M	6	<b>MB225A</b>
MCB 2P 6kA B-32A 2M	6	<b>MB232A</b>
MCB 2P 6kA B-40A 2M	6	<b>MB240A</b>
MCB 2P 6kA B-50A 2M	6	<b>MB250A</b>
MCB 2P 6kA B-63A 2M	6	<b>MB263A</b>



MB310A

**3 pole, Curve B, 6/10 kA**

Description	Pack qty.	Art No.
MCB 3P 6kA B-6A 3M	4	<b>MB306A</b>
MCB 3P 6kA B-10A 3M	4	<b>MB310A</b>
MCB 3P 6kA B-16A 3M	4	<b>MB316A</b>
MCB 3P 6kA B-20A 3M	4	<b>MB320A</b>
MCB 3P 6kA B-25A 3M	4	<b>MB325A</b>
MCB 3P 6kA B-32A 3M	4	<b>MB332A</b>
MCB 3P 6kA B-40A 3M	4	<b>MB340A</b>
MCB 3P 6kA B-50A 3M	4	<b>MB350A</b>
MCB 3P 6kA B-63A 3M	4	<b>MB363A</b>



MB432A

**4 pole, Curve B, 6/10 kA**

Description	Pack qty.	Art No.
MCB 4P 6kA B-6A 4M	3	<b>MB406A</b>
MCB 4P 6kA B-10A 4M	3	<b>MB410A</b>
MCB 4P 6kA B-16A 4M	3	<b>MB416A</b>
MCB 4P 6kA B-20A 4M	3	<b>MB420A</b>
MCB 4P 6kA B-25A 4M	3	<b>MB425A</b>
MCB 4P 6kA B-32A 4M	3	<b>MB432A</b>
MCB 4P 6kA B-40A 4M	3	<b>MB440A</b>
MCB 4P 6kA B-50A 4M	3	<b>MB450A</b>
MCB 4P 6kA B-63A 4M	3	<b>MB463A</b>

### 1 pole, Curve C, 6/10 kA

Description	Pack qty.	Art No.
MCB 1P 6kA C-0.5A 1M	12	<b>MC100A</b>
MCB 1P 6kA C-1A 1M	12	<b>MC101A</b>
MCB 1P 6kA C-2A 1M	12	<b>MC102A</b>
MCB 1P 6kA C-3A 1M	12	<b>MC103A</b>
MCB 1P 6kA C-4A 1M	12	<b>MC104A</b>
MCB 1P 6kA C-6A 1M	12	<b>MC106A</b>
MCB 1P 6kA C-10A 1M	12	<b>MC110A</b>
MCB 1P 6kA C-16A 1M	12	<b>MC116A</b>
MCB 1P 6kA C-20A 1M	12	<b>MC120A</b>
MCB 1P 6kA C-32A 1M	12	<b>MC132A</b>
MCB 1P 6kA C-40A 1M	12	<b>MC140A</b>
MCB 1P 6kA C-50A 1M	12	<b>MC150A</b>
MCB 1P 6kA C-63A 1M	12	<b>MC163A</b>



MC101A

### 2 pole, Curve C, 6/10 kA

Description	Pack qty.	Art No.
MCB 2P 6kA C-0.5A 2M	6	<b>MC200A</b>
MCB 2P 6kA C-1A 2M	6	<b>MC201A</b>
MCB 2P 6kA C-2A 2M	6	<b>MC202A</b>
MCB 2P 6kA C-3A 2M	6	<b>MC203A</b>
MCB 2P 6kA C-4A 2M	6	<b>MC204A</b>
MCB 2P 6kA C-6A 2M	6	<b>MC206A</b>
MCB 2P 6kA C-10A 2M	6	<b>MC210A</b>
MCB 2P 6kA C-16A 2M	6	<b>MC216A</b>
MCB 2P 6kA C-20A 2M	6	<b>MC220A</b>
MCB 2P 6kA C-25A 2M	6	<b>MC225A</b>
MCB 2P 6kA C-32A 2M	6	<b>MC232A</b>
MCB 2P 6kA C-40A 2M	6	<b>MC240A</b>
MCB 2P 6kA C-50A 2M	6	<b>MC250A</b>
MCB 2P 6kA C-63A 2M	6	<b>MC263A</b>



MC204A

### 3 pole, Curve C, 6/10 kA

Description	Pack qty.	Art No.
MCB 3P 6kA C-0.5A 3M	4	<b>MC300A</b>
MCB 3P 6kA C-1A 3M	4	<b>MC301A</b>
MCB 3P 6kA C-2A 3M	4	<b>MC302A</b>
MCB 3P 6kA C-3A 3M	4	<b>MC303A</b>
MCB 3P 6kA C-4A 3M	4	<b>MC304A</b>
MCB 3P 6kA C-6A 3M	4	<b>MC306A</b>
MCB 3P 6kA C-10A 3M	4	<b>MC310A</b>
MCB 3P 6kA C-16A 3M	4	<b>MC316A</b>
MCB 3P 6kA C-20A 3M	4	<b>MC320A</b>
MCB 3P 6kA C-25A 3M	4	<b>MC325A</b>
MCB 3P 6kA C-32A 3M	4	<b>MC332A</b>
MCB 3P 6kA C-40A 3M	4	<b>MC340A</b>
MCB 3P 6kA C-50A 3M	4	<b>MC350A</b>
MCB 3P 6kA C-63A 3M	4	<b>MC363A</b>



MC302A



MC425A

**4 pole, Curve C, 6/10 kA**

Description	Pack qty.	Art No.
MCB 4P 6kA C-0.5A 4M	3	<b>MC400A</b>
MCB 4P 6kA C-1A 4M	3	<b>MC401A</b>
MCB 4P 6kA C-2A 4M	3	<b>MC402A</b>
MCB 4P 6kA C-3A 4M	3	<b>MC403A</b>
MCB 4P 6kA C-4A 4M	3	<b>MC404A</b>
MCB 4P 6kA C-6A 4M	3	<b>MC406A</b>
MCB 4P 6kA C-10A 4M	3	<b>MC410A</b>
MCB 4P 6kA C-16A 4M	3	<b>MC416A</b>
MCB 4P 6kA C-20A 4M	3	<b>MC420A</b>
MCB 4P 6kA C-25A 4M	3	<b>MC425A</b>
MCB 4P 6kA C-32A 4M	3	<b>MC432A</b>
MCB 4P 6kA C-40A 4M	3	<b>MC440A</b>
MCB 4P 6kA C-50A 4M	3	<b>MC450A</b>
MCB 4P 6kA C-63A 4M	3	<b>MC463A</b>